





AN EXCHANGE OF TECHNICAL INFORMATION

Number: TL011 - 2022
Subject: NaturaLINE Compressor Icing

Released: December 09, 2022

Compressor icing can occur on the suction line and the compressor end bell when running at low cargo setpoints at lower ambient and higher humidity conditions. This operation is normal and will not affect the reliability of the unit. For awareness, we have placed a label on the front of the unit. If your unit does not have the label, contact your Carrier Field Engineering Manager and one will be provided.



CTD PART NO.: 62-66170-00

Service Engineering / Container Products

Please circulate copies of this bulletin to all service and management personnel as soon as possible.